# SONY



### \* Display sold separately.



CD-RV

### **FEATURES**

- Intel<sup>®</sup> Pentium<sup>®</sup> 4 Processor 2A<sup>ttt</sup> GHz<sup>1</sup>
- 512MB PC-2100 DDR (expandable to 1GB)
- 400MHz Front Side Bus
- 60GB<sup>++</sup> Ultra ATA/100 Hard Drive
- CD-RW Drive Create your own CDs!
- DVD-ROM
- · Music, Movies, and Photo Software:
  - DVgate
  - MovieShaker<sup>™</sup>
  - SonicStage<sup>™</sup> for VAIO<sup>®</sup>
  - PowerDVD
- Memory Stick<sup>®</sup> Media Slot
- Front and Rear Accessible i.LINK (IEEE 1394) Interfaces and USB Connections<sup>1</sup>
- · High-Speed Internet Ready with 10 Base-T/100Base-TX Fast Ethernet

Sony Electronics Inc.

Information Technology Product Division 16765 West Bernardo Drive, San Diego, CA 92127 For more information: 1.800.4SONYPC (476-6972) Web address: http://www.sony.com/vaio

Web address: The topy-use industry loss standards, and therefore, there are a multitude of varying software packages and ad-on hardware options. This personal computer is not manufactured to any specific software, and Sory does not and cannot make any warranty or representation with respect to the performance of this product with any particular software packages and/or non-Sory ad-on hardware option except those mentioned in this document. Sory hereby disclaims any representations or warranty that this product is compatible with any combination of non-Sory ad-on hardware option except those mentioned in this document. Sory hereby disclaims any representations or warranty that this product is compatible with any combination of non-Sory products you may choose to connect. While Sory representatives or Sony authorized dealers may be able to assist you and may make recommendations, they are NOT authorized to vary or waive this disclaimer. Purchasers must determine for themselves the subtability and compatibility of the hardware and software in each and every particular instance. Some pre-installed software titles may not include full documentation. Software titles pre-installed on the Sory Desktop Computer are subject to change without notice. Simulated graphic shown on display.

Window Induce. Similates graphic shown of usplay. @2002 Sony Electronics Inc. All lights reserved. Reproduction in whole or in part without written permission is prohibited. Sony, ILINK, VAIO Digital Studio, VAIO Smart, SonicStage MoveShaker, and VAIO are trademarks of Sony. Intel and Pentium are registered trademarks of Intel Corporation. Microsoft, Windows and Outlook are trademarks of Microsoft Corporation. All other trademarks are trademarks of their respective owners. This product meets the standards of the International Energy Star Program for energy efficiency. Features and specifications are subject to change without notice. Weights and measurements are approximate.

## PCV-RX755 Sony VAIO<sup>®</sup> Digital Studio<sup>™</sup> PC

- CD-RW Drive Create your own CDs!
- Intel<sup>®</sup> Pentium<sup>®</sup> 4 Processor 2A<sup>ttt</sup> GHz<sup>t</sup>
- 512MB PC-2100 DDR / 60GB<sup>tt</sup> Hard Drive
- DVD-ROM Drive  $\checkmark$
- High-speed Internet Readv with 10Base-T/100Base-TX Fast Ethernet
- i.LINK® (IEEE 1394) Interface and USB Connectors<sup>1</sup>



### **SPECIFICATIONS**

Intel® Pentium® 4 Processor 2A\*\*\* GHz\*

#### Model PCV-RX755

Processor

CACHE MEMORY 512KB Integrated On-Die Level 2 FRONT SIDE BUS SPEED 400MHz STANDARD RAM 512MB PC-2100 DDR (expandable to 1GB) HARD DRIVE 60GB<sup>++</sup> Ultra ATA/100 Hard Drive **CD-RW** DRIVE CD-RW (24X max. write / 10X max. rewrite / 40X max. read) DVD-ROM DRIVE 16X max. DVD-ROM Read / 40X max. CD-ROM Read FLOPPY DISK DRIVE 3.5" 1.44 MB Floppy Disk Drive VIDEO & GRAPHICS SIS650 Integrated Graphics with Real256™ 2D/3D Graphics Accelerator 32MB Shared Graphics Memory (64MB Max.) ETHERNET 10Base-T/100Base-TX Fast Ethernet MODEM V.90 compatible data/fax modem EXPANSION SLOTS One AGP Three PCI (one occupied by Modem) Memory Stick® Media Slot EXPANSION BAYS Two 5.25" Half-Height (two occupied) One External 3.5" (occupied) Two Internal 3.5" (one occupied) PORT CONNECTORS Four USB (two front/two rear) Two PS/2® (Mouse/Keyboard) One VGA monitor port One Serial / One Parallel One 6pin i.LINK port (rear) One 4pin i.LINK port (front) One Headphone / One Microphone One Line İn SUPPLIED ACCESSORIES Speakers (Stereo) VAIO Smart<sup>™</sup> Keyboard PS/2<sup>®</sup> Wheel Mouse RJ-11 Phone Cord Power Cord **Power Requirements** 100-120V -3A (50/60Hz) **Power MANAGEMENT** ACPI 1.0 Compliant

DIMENSIONS (CPU) 8.0"(W) x 14.2"(H) x 14.6"(D) WEIGHT (CPU) 28.5 lbs. SERVICE One Year Limited Express Repair Service (upon registration; 90 days without registration)\* LIMITED WARRANTY One Year Parts and Labor (upon registration; 90 days without registration)\* **TELEPHONE SUPPORT** Hardware: One Year Software and Operating System: 90 Days PRE-INSTALLED SOFTWARE **OPERATING SYSTEM** Microsoft® Windows® XP Home Edition Sony PCs use Genuine Microsoft® Windows® Operating Systems www.microsoft.com/piracy/howtotell SONY ORIGINAL SOFTWARE DVgate" SonicStage<sup>™</sup> for VAIO<sup>®</sup> MovieShaker Smart Capture DigitalPrint PowerDVD **OTHER SOFTWARE APPLICATIONS** Corel WordPerfect® Office 2002 Adobe® Photoshop® Elements Adobe® Acrobat® Reader® Apple QuickTime® Intuit Ouicken® 2002<sup>2</sup> Microsoft® Outlook® Express ANTI-VIRUS & RECOVERY SOFTWARE Trend Micro PC-Cillin® Sony Application Recovery CD(s) Sony System Recovery CD(s) ONI INF CENTER VAIO Support Agent America Online® Farthl ink TotalAccess<sup>\*\*\*</sup>

### player\*

- † GHz denotes microprocessor internal clock speed; other factors may
- affect application performance. #1 GB means one billion bytes when referring to Hard Drive capacity. Accessible capacity may vary. #11 Naming of 2GHz, based on .13 micron core and secondary cache of
- 512KB
- Certain restrictions apply. Requires payment of additional fees or subscription for use 1 i.LINK is a trademark of Sony used only to designate that a product contains an IEEE 1394 connector. All products with an i.LINK connector may not communicate with each other.
  Previous Quicken users may require additional upgrade.